


Restoration&Moisture&Ventilation



SPARE PARTS LIST

PureAiro HEPA Max 870



NO.	NAME MODEL	MATERIAL	QUANTITY
1	Dust Cap	Plastic	1
2	Bridle Line	Polyamides	1
3	Power Cord Fastener	Polyamides	4
4	Cover Upper	LLDPE	1
5	R Type Clamp	Plastic	1
6	G3 Filter	Module	1
7	Compound Filter Screen	Module	1
8	Uv Lamp	Module	1
9	Lamp Card Buckle	Stainless Steel	2
10	Guide Solar Or Lunar Halo	ABS	1
11	Motor	Stainless Steel	1
12	The Motor Bracket	Stainless Steel	1
13	The Differential Joint	Copper	2
14	Handle	Plastic	1
15	Air Outlet Dust Rack	Steel Net	1
16	Air Outlet Support	ABS	1
17	Lower Casing	LLDPE	1
18	Foot Pad	TPV	12
19	The Power Cord Buckle	Polyamides	1
20	Ballast Assembly	Module	1
21	Protective Ring	Plastic	2
22	Electric Control Box	Galvanized Sheet	1
23	Pressure Difference Switch	Plastic	1
24	Capacitor Clamp	Sheet Iron	1
25	Main Control Panel	PCB	1
26	Capacitance	Module	1
27	Rotary Knob	Plastic	1
28	GFCI Outlet	Module	1
29	Control Panel	Sheet Iron	1
30	Indicator Lamp	Module	1
31	Timer	Module	1
32	Overload Protection Switch	Module	1